Natural Gas Savings for Steel Heat-Treating: Proven Measures and a CHP Microturbine Option

Infinity Turbine LLC

[TEL] +1-608-238-6001 (Chicago

[Email] greg@infinityturbine.com

https://infinityturbine.com/heat-treating-steel-ng-savings-using-microturbine-by-infinity-turbine.html

How a steel heat-treating plant can reduce natural-gas consumption: combustion tuning, air preheat, waste-heat recovery, scheduling, insulation, and combined heat and power (microturbine exhaust for tempering). Includes quick ROI cues and process limits.

This webpage QR code

PDF Version of the webpage (maximum 10 pages)

Natural Gas Savings for Steel Heat-Treating: Proven Measures and a CHP Microturbine Option

1) Low-friction savings (controls and tuning)

These are usually the fastest paybacks.

Excess-air and O_2-trim control: Tighten furnace excess air (e.g., from 20–30% down toward 10–15% where safe). Every 10% too much excess air can add ~1–2% to fuel use via stack losses. Add continuous O_2 trim on key furnaces.
Burner tune-ups & staging: Annual combustion tuning; consider staged or low-NOx burners that maintain efficiency over a wider turndown.
Pressure management & infiltration: Keep slight positive furnace pressure and fix door/leak paths. Cold air infiltration is a hidden fuel sink.
Fan/VFD optimization: Add VFDs to recirculation and exhaust fans to modulate only what you need—less over-venting = less fuel.

Typical impact: 5–15% fuel reduction across a bank of furnaces.

2) Heat where it helps most: air and load preheat

Recovering sensible heat from hot exhaust is the biggest lever in fired heat-treat.

Recuperators (air-to-air): Preheat combustion air using flue gas.
– Basic recuperators can lift air to 200–400 °C → 10–25% fuel savings.
– High-efficiency metallic/ceramic units can do better if temps allow.
Regenerative burners: Paired beds that swap hot/cold sides every ~20–60 s; combustion air preheat can reach 800–1,000 °C. 30–50% fuel reduction is common on continuous lines (capital is higher).
Load/charge preheaters: Use exhaust to preheat the steel (or trays) upstream; even 100–200 °C preheat trims soak time and burner duty.
Radiant-tube recuperators: On sealed/quench or atmosphere furnaces with radiant tubes, fit recuperative tubes to claw back tube exhaust heat.

Rule of thumb: Every 100 °C of combustion-air preheat can cut main-burner fuel ~5–7%, depending on furnace type.

3) Scheduling, recipes, and “time at temperature”

Batch consolidation: Run at higher load density and fewer idles. Idling a hot furnace is expensive; use smart start/stop to minimize “hot idle” hours.
Cycle optimization: Verify metallurgical requirements for soak time and ramp rates; many lines run conservative cycles that can be tightened with trials and hardness data.
Door discipline: Minimize openings; add quick-acting doors and better seals.

Typical impact: 5–10% fuel reduction without capital spend.

4) Thermal envelope improvements